Filter change

WO-041 / May 4, 2026

SCHEDULED SERVICE

Work requested

Replace the inlet filter and inspect the filter housing.

Work performed

Removed the used cartridge. Cleaned the seat and installed a new cartridge.

Return to service

Completed a ten-minute run. No leakage at the housing.

Seal replacement

WO-052 / June 1, 2026

CORRECTIVE SERVICE

Work requested

Inspect seepage at the seal cover.

Work performed

Removed the worn seal and fitted a replacement from stores.

Return to service

Completed a fifteen-minute run. The cover remained dry.

Pump inspection

May 5, 2026 / Round 1

FIELD INSPECTION

Inlet pressure	18 psi
Inlet strainer	Clear
Seal cover	Dry
Follow-up	After filter change

Pump inspection

May 19, 2026 / Round 2

FIELD INSPECTION

Inlet pressure	19 psi
Inlet strainer	Clear
Seal cover	Trace at cover
Follow-up	Monitor seal cover

Pump inspection

June 2, 2026 / Round 3

FIELD INSPECTION

Inlet pressure	18 psi
Inlet strainer	Clear
Seal cover	Dry
Follow-up	After seal replacement

Parts ledger

May 2026 / Unit P-04

STORES REGISTER

Day	Part	Movement	Quantity
04	Inlet filter	Issue	1
04	Housing gasket	Issue	1
06	Inlet filter	Receipt	6
19	Absorbent pad	Issue	2

Parts ledger

June 2026 / Unit P-04

STORES REGISTER

Day	Part	Movement	Quantity
01	Pump seal	Issue	1
01	Cover gasket	Issue	1
02	Absorbent pad	Issue	1
04	Pump seal	Receipt	3