Filter change

WO-041 / May 4, 2026

SCHEDULED SERVICE

Work requested

Replace the inlet filter and inspect the filter housing.

Work performed

Removed the used cartridge. Cleaned the seat and installed a new cartridge.

Return to service

Completed a ten-minute run. No leakage at the housing.

Seal replacement

WO-052 / June 1, 2026

CORRECTIVE SERVICE

Work requested

Inspect seepage at the seal cover.

Work performed

Removed the worn seal and fitted a replacement from stores.

Return to service

Completed a fifteen-minute run. The cover remained dry.